

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4497	DATE	2019/5/28
MANUFACTURE	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	Improper adjustment of the brake valve. There is a risk that the brake will stay on and snowplows will not move forward even if accelerator is depressed.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
UDS-NR6B	NR302	2013~2016	215	
UDS-NR6B	NRN302	2013~2014	2	
NRNB	NRNS302	2015	3	
NR6B	NR302BC	2016	1	
YDS-NR6B	NR303	2016	22	
NRNB	NRNS303	2016	1	
UDS-NR7B	NR402	2013~2014	20	
YDS-NR7B	NR403	2016	8	