

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2850	Date	May 29, 2019
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the process of manufacturing the inflator for the driver's seat airbag, due to inadequate humidity control of gas generates, some gas expansion agent are sealed in a moisture-containing condition. As a result, if a large temperature change is repeated, deterioration of the gas generating agent is promoted, an expansion force more than expected is generated at the time of air bag deployment, and the inflator container may be damaged.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-1JBFQ	VW Golf 1.6	MY2003	4
GH-3BAZM	VW Passat 2.0	MY2003	1
		Total	5