

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.		DATE	May 30, 2019
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to improper cooling process during the tempered glass manufacturing, certain rear door glass on the left side has not been properly tempered. Such problem has occurred in the cause of insufficient cooling procedure after the glass-forming. Therefore, it may not meet fracture-test requirements of tempered glass prescribed by the Japan Safety Regulations Article 29.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA – GT2	「IMPREZA」	2018	21
DBA – GT3			23
DBA – GT6			4
DBA – GT7			10
DBA – GT3	「XV」		10
DBA – GT7			31
		TOTAL	99