

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4510	DATE	June 6 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		The subject matter relates to a Getting on or off Indicator mounted on buses. Due to a fault in a circuit designed to indicate the SOS mode, when it indicates the SOS with the rear door opened, as a result, there could be the door does not close.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-LV290N2 2KG-LV290N2 2PG-LV290N2	[ERGA]	2017-2019	134
2PG-LV290Q2 2TG-LV290Q2		2017-2018	20
2KG-LR290J3	[ERGA MIO]	2017-2019	33
		TOTAL	187

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Getting on or off Indicator	PL-1000	2017	1
		TOTAL	1