
VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	4511	DATE	Jun. 6. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	The subject matter relates to a Getting on or off Indicator mounted on buses. Due to a fault in a circuit designed to indicate the SOS mode, when it indicates the SOS with the rear door opened, as a result, there could be the door does not close.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-KV290N2	[HINO Blue Ribbon]	2017~2018	35
2KG-KV290N2			
2KG-KV290Q2		2017~2018	10
2PG-KV290Q2			
2TG-KV290Q2			
2KG-KR290J3	[HINO Rainbow]	2018~2019	22
		TOTAL	67