

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-2862	DATE	June 11, 2019
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	On affected vehicles, a possible non-compliance involving the software for the built-in systems interface (BSI) and engine relay unit (BSM) could disrupt the operation of the lighting. The operation involves downloading the BSI and BSM software, and replacing the BSM if necessary.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-W2AH02	PEUGEOT 508	2015-2016	125
LDA-W2WAH02			175
		TOTAL	300