

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2863	DATE	14 th June 2019
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.)		
DESCRIPTION OF DEFECT	The coolant hose between the radiator and expansion tank may have been incorrectly routed during assembly.		

EBL-HJ1200	Thrupton	2016 - 2017	77
	Thrupton R	2016 - 2017	273
2BL-DHJ1200	Thrupton	2017 - 2018	6
	Thrupton R	2017 - 2018	125
TOTAL			481