

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2870	DATE	June 17 th , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The airbag module of driver's airbag might not be manufactured according to the specification, caused by inappropriate manufacturing process. Thus, in the case of an activation of the airbag, the generator may burst and metal parts could pass through the airbag cushion material.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-TX20	BMW X3 xDrive 20d	2018	2
		TOTAL	2