

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2866	DATE	Jun. 26, 2019
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>The reversing lights are not activated until approx. 5 seconds after starting the engine due to the control logic.</p> <p>The onboard supply control unit must be coded on the affected vehicles.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-8VCXS	Audi A3 SB 1.4T 90kw	2017 – 2018	1,987
DBA-8VCXSL	Audi A3 Sedan 90kw	2017 – 2018	1,067
		Total	3,054