

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2876	DATE	June 27,2019
MANUFACTURER	HONDA CANADA INC.		
DESCRIPTION OF DEFECT	In certain the passenger's airbag inflators, gas generating propellant may get deteriorated through repetition of environmental temperature and humidity fluctuations. This can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator whereby the container of inflator could be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-YD1	「MDX」	2003	515
		TOTAL	515