

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2877	DATE	June 27,2019
MANUFACTURER	HONDA AUTOMOBILE (THAILAND) CO., LTD.		
DESCRIPTION OF DEFECT	In certain the passenger's airbag inflators, gas generating propellant may get deteriorated through repetition of environmental temperature and humidity fluctuations. This can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator whereby the container of inflator could be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-GD6	「FIT ARIA」	2002～2004	1,860
DBA-GD6		2004～2005	471
LA-GD7		2003～2004	366
DBA-GD7		2004～2005	127
LA-GD8		2002～2004	3,976
DBA-GD8		2004～2008	2,753
LA-GD9		2003～2004	473
DBA-GD9		2004～2008	770
		TOTAL	10,796