

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4516	DATE	June 28,2019
MANUFACTURER	Mazda E&T Co.,Ltd.		
DESCRIPTION OF DEFECT	Regarding the vehicle with a boarding slope device for wheelchairs, the brake piping of a rear wheel is wrongly arranged due to the improper arrangement design of it. Therefore, the sideslip prevention device doesn't function properly when the vehicle sideslips at the time of turning for example, which may impair the running stability in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-DA17W (revision)	Suzuki Every	2015 – 2019	2,904
ABA-DR17W (revision)	Nissan NV100 Clipper Rio	2016 – 2019	1,811
TOTAL			4,715