

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -2882	DATE	June xx, 2019
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Incorrect fastening nuts were used to fasten the drive shaft to the wheel hub on the rear axle. As a result, the required tightening torque was not achieved during assembly of the components, which does not ensure sufficient tightness of the screw connection between the drive shaft and wheel hub.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-991MA175-	911 GT3RS	2019	2
		TOTAL	2