

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4536	DATE	July.17.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the molding of the quarter window glass installed rear on the rear door, due to improper molding condition, there is a possibility that the molding may not adequately adhere to the quarter window glass. In this condition, the molding may peel from the quarter window glass due to wind pressure while driving etc., causing abnormal noise. If the vehicle is continuously operated in this condition, in the worst case, the molding could separate from the quarter window glass.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6AA-AZSH20	[CROWN]	2018	6,120	RS grade
6AA-AZSH21			940	
6AA-GWS224			1,744	
3BA-ARS220			884	
		TOTAL	9,688	