

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 5 3 5	DATE	July. 18. 2019
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding parking cable of transmission device, the bush in the shift lever end for cable deteriorates by hydrolysis due to the inappropriate material. Therefore, the bush is broken and the cable detach from the shift lever. In this case, parking lock cannot be operated, in the worst case, the engine may not be able to be started with no parking lock activation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAA-ME0	e-NV200	2 0 1 4	1, 0 8 1
ZAB-VME0		~ 2 0 1 7	1, 3 8 7
		TOTAL	2, 4 6 8