

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4537	DATE	July 18, 2019
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	Transmission control computer with automatic transmission with vehicle, due to inappropriate clutch control program, if noise of range signal is detected while driving with D-position (including Manual mode), unintended clutch control may be operated. Therefore, the shock may occur with decelerating, in the worst case, losing the driving stability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-NF2EK	「Abarth 124 Spider」	2016-2019	730
		Total	730