

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4532	DATE	Jul.19,2019
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>On some wheel crane power transmission devices, the amount of screw locking agent coating applied to the output flange installation bolts was inadequate due to inadequate education of a torque converter assembly worker. Therefore the bolt may loosen with travel related vibrations and, with continued use in this condition, the bolt may fall off resulting in the flange also falling off making travel impossible in the worst cases.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
SD-T002	TADANO 「CREVO 160」	2004-2008	12
JDS-T006	TADANO 「GR-160N-2」 「GR-120NDW-2」	2009-2013	34
UDS-T009	TADANO 「GR-160N-3」	2014-2017	16
YDS-T014	TADANO 「GR-160N-4」	2017-2018	4
SD-EW05	KOBELCO 「RK160-5」	2007	1
JDS-EW06	KOBELCO 「RK160-6」	2012	4
UDS-EW07	KOBELCO 「RK160-7」	2014-2016	4
YDS-EW08	KOBELCO 「RK160-8」	2018	1
		TOTAL	76