

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	GAI-2888	DATE	Jul.19,2019
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	Some crane axles have insufficient knuckle thickness due to inappropriate design instructions. Therefore, with long term continued use in this condition, the upper part of the knuckle may crack and, in the worst cases, normal steering may not be possible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
FAUN	「ATF400G-6」	2016-2018	18
FAUN	「ATF220G-5」	2016-2018	17
FAUN	「ATF160G-5」	2016-2017	7
FAUN	「ATF130G-5」	2015-2018	29
		TOTAL	71