VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2883	DATE	24.07.2019	
MANUFACTURER	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)			
DESCRIPTION OF DEFECT	(Japanese Importer: Ferrari Japan K.K.) A possible non-conformity of the Air Bag and the seat I pretensioners electronic control unit (ECU) could lead, due to potent power supply failure, to the following events: -The Air Bags and/or the seat belt pretensioners could be deactivate the Air Bag warning light on the instrument panel will activate -The vehicle's Air Bags and/or the seat belt pretensioners in inadvertently activate. This potential non-conformity of the Air Bag ECU may increase the of injury and/or possibility of an accident.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-F142VS	458Speciale	2015	4
ABA-F142ADL	458Speciale A	2015	15
ABA-F142B	488GTB,488Spider,J50	2015-2018	88
ABA-F149DD	California T	2015-2017	57
ABA-F152	F12berlinetta	2015-2016	21
ABA-F152ACL	F12tdf	2016	1
		TOTAL	186