

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4543	DATE	July 25, 2019
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	In the affected inside rearview mirror, due to the inappropriate method to adhere the mirror plate to mirror holder, some of them may adhere poorly to each other. As a result, the mirror plate may separate from the mirror holder and move over slightly. In the worst case, the mirror plate may fall off the mirror holder, causing the operator not to confirm the following traffic scene.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-BP5P	Mazda「MAZDA3」	2019	115
		Total	115