

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2892	DATE	July 25 <sup>th</sup> , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	A replacement part (steering wheel with Takata airbag, or the airbag inflator itself) relevant to former recalls may possibly have been installed, since they are compatible with the originally installed parts. It cannot be ruled out that, in case the airbag is activated during a crash, the inflator ruptures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-DT25	BMW 525i	2000 - 2003	4,126
GH-DS25	BMW 525i Touring	2000 - 2003	468
GH-DT30	BMW 530i	2000 - 2003	1,934
GH-DS30	BMW 530i Touring	2000 - 2003	248
GH-DN44	BMW 540iA	2000 - 2003	186
GH-FA30	BMW X5	2001 - 2003	1,236
GH-FA30A		2001 - 2003	15
GH-FB44		2000 - 2003	330
GH-FB44A		2001 - 2003	8
GH-FA30N	BMW X5 3.0	2003	8
GH-FB44N	BMW X5 4.4	2003	1
GH-PA25	BMW X3 2.5	2004 - 2005	1,400
GH-PA30	BMW X3 3.0	2004 - 2005	522
		TOTAL	10,482