

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import~~ Import Vehicles

CAMPAIGN No.	Gai-2893	DATE	July, 29 <sup>th</sup> , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate drawing instruction by the supplier, the stamp on the alloy wheels, which is indicating the flange configuration, is missing. This does not comply with the Japanese regulation article 9.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CLA-2Z15U	BMW i8 Roadster	2018	24
	BMW i8 Coupe	2018	1
TOTAL			25