

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	4 5 4 1	DATE	August 1, 2019
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	<p>①In the transmission of the agricultural tractor, the transmission wear progresses due to large speed reduction operation because the control program for shifting is inappropriate. Therefore, the use in the condition may lead to progresses the wear, becomes impossible to shift, and in the worst case scenario, the tractor can not run.</p> <p>②In the transmission of the agricultural tractor, the tractor becomes impossible to run by detecting pressure abnormality under specific conditions because the control program for shift pressure is inappropriate.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	「TJV755」	2018-2019	37 ①37 ②36
	「MF4507J」	2019	1 ①1
—	「TJV655」	2018-2019	26 ①26 ②26
	「TJV655R」	2018-2019	2 ①2 ②2
		TOTAL	66 ①66 ②64