

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4546	DATE	August 1 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>On certain mechanical automatic transmissions of middle duty buses, because the setting of the program inputting equipment for the gear positioning sensor is inappropriate, temperature correction values may not be input in the gear positioning sensor. Therefore, when driving on an uphill road etc. and the temperature of the sensor rises high, the sensor may become unable to output correctly, resulting the warning light to illuminate and the gear unable to be shifted.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-RR2AJDJ	[ISUZU GALA MIO]	2019	1
		TOTAL	1