

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

| | | | |
|-----------------------|---|------|------------------|
| CAMPAIGN No. | gai-2894 | DATE | August 21 , 2019 |
| MANUFACTURER | RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.) | | |
| DESCRIPTION OF DEFECT | Battery harness may be broken due to wrong routing. As the worst case, fuse could be brown, instrument panel could turn on the warning lamp, and engine may stop. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------|-----------------|---------------------|-------------------|
| ABA-BBM5P | 「MEGANE R.S.」 | 2018 | 97 |
| | | TOTAL | 97 |