

第4号様式 (英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4554	DATE	Aug, 23, 2019
MANUFACTURER	Fuji Car Manufacturing Co., Ltd. 13-1 Chishiro-cho, Moriyama-city, Shiga, 524-0034, Japan		
DESCRIPTION OF DEFECT	Regarding of the vehicles equipped with liquefied natural gas (LPG) , tank some vehicles combination lamps obstruct the outside visible angle of the combination lamp at the rear side of the vehicles because the lamp installation place design was inappropriate. Because of that, there is a risk that the outside visible angle of the turn signals at rear side does not meet the standards for safety and security section 41 (the standard of the turn signal).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-NKR81AN	Isuzu Elf	2006	1
PB-NKR81N		2006~2007	2
PDG-NKR85YN		2007~2011	19
SKG-NKR85YN		2011~2014	13
TKG-NKR85AN		2013~2017	5
TKG-NKR85YN		2015~2016	8
TPG-NKR85AN		2016~2017	2
TPG-NKR85N		2016~2018	6
TPG-NKR85YN		2018	1
TPG-NMR85N		2016~2018	4
BDG-XZU388M		Hino Dutro	2007
LD-BZU340M	2006		3
PB-XZU331M	2006		1
PB-XZU334M	2006		1
		TOTAL	67

(日本工業規格A列4番)

備考 不具合箇所が複数ある場合であって対象車が異なる場合には、それを区別して記載すること。