VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2908	DATE	Aug.28.2019
MANUFACTURER	NUMMI (TOYOTA)		
DESCRIPTION OF DEFECT	In the front passenger airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UA-ZZE136	[VOLTZ]	2002-2004	929
TA-ZZE137			312
UA-ZZE138			522
		TOTAL	1,763