## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Import Vehicles

CAMPAIN No.	Gai –2906	DATE	2 September, 2019	
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG			
	(Japanese Importer: Porsche Japan KK)			
DESCRIPTION OF DEFECT	For vehicles configured without Porsche Communication			
	Management (PCM), instead of the woofer a cover for the			
	loudspeaker opening in the door sub-frame has to be			
	installed. Due to an allocation error, it is possible that this			
	cover was not installed in the affected vehicles.			
	This leads to a different air pressure difference within the			
	door. The pressure difference is used as an input variable for			
	the crash sensors and thus for triggering restraint systems.			
	Under certain cir	rcumstances, t	he deviating pressure	
	difference can affect the triggering of the restraint systems.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-991J4	911 Carrera T	2019	2
		TOTAL	2