

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic vehicles

CAMPAIGN No.	4564	DATE	September 3, 2019	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	<p>With regards to the driver support system for heavy-duty tractors, due to an inappropriate Driver Assistance Control Unit software program which was installed after the previously notified improvement campaign (KAI 546) began, when trailers without Anti-lock Brake System (ABS) are connected, the expected "Traffic Eye Brake (TEB) inactive message" may not be displayed. Thus, the driver may not be able to recognize inoperable TEB.</p>			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-GK5AAB 2PG-GK5AABKai	Quon	2017 - 2018	1,089	
2PG-GK5AAD		2017 - 2018	423	
2PG-GK5AAE		2017 - 2018	82	
2PG-GK5AAK		2018	1	
		TOTAL	1,595	