

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	外-2903	Date	Sep 4, 2019
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	Electrical wiring connected to engine controller may interfere agianst the close routed hydraulic hose and worn. Then, Engine controller will detect certain error and may induce engine runnig.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-LTE	「926M」	2016-2017	68
YDR-KTG	「930M」	2016-2017	44
YDS-J3R	「938M」	2016-2017	38
		TOTAL	150