

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4559	DATE	Sep.5, 2019
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Nuts for the exhaust pipe front were tightened with insufficient torque value due to inappropriate instructions of tightening torque. Therefore, it may lead nuts to be loosened from driving vibration or other potential factors, and in the worst case, exhaust gas may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA - VAG	「WRX」	2015 ~ 2017	10,197
DBA - VMG	「LEVORG」	2015 ~ 2017	11,715
DBA - SJG	「FORESTER」	2015 ~ 2018	10,314
		TOTAL	32,226