

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 5 6 2	DATE	Sep. 5. 2019
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Regarding the harness of PTC heater which support heater system, because the harness wire size is small inappropriately, if PTC heater operates continuously at maximum output, connector female terminal may be deformed by heat generation. Therefore, if the PTC heater is used continuously in this condition, terminal becomes extremely hot and connector may be burned out, in the worst case, it may lead to a thermal incident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
LDF-VW6E26	N I S S A N N V 3 5 0 C A R A V A N	2 0 1 2 ~ 2 0 1 9	18,072
LDF-VW2E26			2,307
LDF-CW8E26			7,135
LDF-CW4E26			341
LDF-DW4E26			244
LDF-JVW6E26	I S U Z U C O M O	2 0 1 2 ~ 2 0 1 9	282
LDF-JVW2E26			52
LDF-JCW8E26			48
LDF-JCW4E26			4
		TOTAL	28,485