

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-2915	DATE	17/09/2019
MANUFACTURE	McLaren (Japanese Importer : McLaren Automotive Asia Pte Ltd)		
DESCRIPTION OF DEFECT	In the event that chafing of the engine harness bundle results in damage to the wires contained within, there are a number of possible consequences, depending on the wire(s) that are damaged. Potential consequences are: the car entering idle limp mode (significant engine power reduction), torque limitation (slight engine power reduction), engine stall, engine misfire, and unburnt fuel in the catalyst that could lead to increased temperature of the catalyst.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-P15S	「McLaren Senna」	2018	26
		TOTAL	26