

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2917	DATE	Sep. 19, 2019
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	In the mechatronics of 7 speed S-tronic automatic transmission, due to the Inappropriate threading of the upper housing, some are lacking in durability. As a result, due to continuous accumulation of hydraulic pressure change, the upper housing may be cracked, and in the worst case, the driving force cannot be transmitted and the vehicle cannot be driven, because of insufficient hydraulic pressure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8JCDA	Audi TT Coupe 1.8	2013-2014	1,936
ABA-8PCAX	Audi A3 1.4TFSI	2009-2010	3,418
ABA-8PCDA	Audi A3 1.8	2009-2012	1,143
ABA-8XCTH	Audi A1 1.4/136kw	2014-2014	150
DBA-8PCAX	Audi A3 1.4TFSI	2010-2013	5,854
DBA-8VCPT	Audi A3 SB 1.4T 103kw	2014-2015	1,302
DBA-8VCPTL	Audi A3 Sedan 103kw	2014-2015	762
DBA-8VCXS	Audi A3 SB 1.4T 90kw	2014-2015	5,959
DBA-8VCXSL	Audi A3 Sedan 90kw	2014-2015	3,259
DBA-8XCAX	Audi A1 1.4/90kw	2011-2014	11,067
DBA-8XCPT	Audi A1 1.4/103kw	2014-2014	361
		Total	35,211