

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2928	DATE	September 25 <sup>th</sup> , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	A protective plate for the high pressure pump has not been installed. In case of a related accident, this may lead to damage to the high pressure pump and thus a possible fuel leak, which may result in a risk of fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-YS15	MINI ONE Crossover	2017 - 2018	537
	MINI Cooper Crossover	2017 - 2018	111
		TOTAL	648