

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2919	DATE	Sep. 26, 2019
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	It is possible that the latching connection on the wheel housing liner may fail. As a result, the wheel arch cover may come loose and, in individual cases, become detached from the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-FYDAXA	Audi Q5 45Tq Air suspension	2018-2019	456
DBA-FYDAXS	Audi Q5 45Tq	2018-2019	543
LDA-FYDETA	Audi Q5 40TDIq Air suspension	2019	37
LDA-FYDETS	Audi Q5 40TDIq	2019	371
		Total	1,307