

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2920	DATE	Sep. 26, 2019
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	It is possible that the latching connection on the wheel housing liner may fail. As a result, the wheel arch cover may come loose and, in the worst case, become detached from the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FYCWGA	Audi SQ5 Air suspension	2019	37
ABA-FYCWGS	Audi SQ5	2018-2019	495
DBA-FYDAXA	Audi Q5 45Tq Air suspension	2018-2019	88
DBA-FYDAXS	Audi Q5 45Tq	2017-2019	2,142
LDA-FYDETA	Audi Q5 40TDIq Air suspension	2019	9
LDA-FYDETS	Audi Q5 40TDIq	2019	114
		Total	2,885