

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles)

CAMPAIGN No.	Gai-2926	DATE	2019/9/26
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain S-Class vehicles (222 platforms) the covers on the A, B and C pillars might be installed incorrectly. In the event of an accident with activation of the curtain airbag, an incorrectly installed pillar cover might detach and enter the passenger compartment, increasing the risk of injury to vehicle occupants. Furthermore, the curtain airbag might not deploy as intended and may not provide its specified protection potential to occupants in a crash increasing the risk of injury for the respective passenger.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-222058	S450	2019	1
DBA-222983C	Mercedes-Maybach S560		1
		TOTAL	2