

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4573	DATE	Sep.27,2019
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>The hydraulic oil line filters on some wheel cranes are not strong enough as they were assembled with non-conformant filter head material. This condition may result in hydraulic leaks from damaged line filters, and in the worst cases, the line filter may fall off and hinder other traffic. In some vehicle types, this may result in an increase in the steering force.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDR-T015	TADANO 「GR-130N-2」	2017-2019	204
YDS-T014	TADANO 「GR-160N-4」	2017-2019	331
YDS-T012	TADANO 「GR-250N-4」	2016-2019	831
YDS-T016	TADANO 「GR-600N-3」	2018-2019	92
YDS-T013	TADANO 「GR-700N-2」 「GR-1000N-1」	2016-2019	470
YDR-EK06	KOBELCO 「RK130-2」	2019	1
YDS-EW08	KOBELCO 「RK160-8」	2017-2019	13
YDS-EE05	KOBELCO 「RK250-9」	2017-2019	47
YDS-EG05	KOBELCO 「RK700-3」	2017-2019	19
		TOTAL	2008