

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-2930	DATE	As soon as ready
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : PEUGEOT CITROËN JAPON Co.,Ltd.)		
DESCRIPTION OF DEFECT	In the joint of tailgate strut, some tailgate strut and tailgate interfere at the time of opening / closing of tailgate due to insufficient verification of parts characteristics. Therefore, the joint is overloaded and the tailgate strut unclip from the joint and in the worst case, the tailgate may fall. The countermeasure is to check the clearance between the tailgate strut and the tailgate. If there are interference, change the position of tailgate strut joint. If there is any damage on the tailgate strut joint, replace with a new tailgate strut.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-R85G06	PEUGEOT 508	2018-2019	94
3DA-R8AH01			198
		TOTAL	292