

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4566	DATE	Oct. 2. 2019
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain air circuits for brake operation of heavy duty trucks, due to insufficient durability evaluation of the air tank for regenerating the desiccant, the air tank may crack, causing a leak of air. Therefore, an air leak noise may be made or the alarm buzzer may operate, resulting the brake effectiveness to deteriorate if it is continued to be used under the condition.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FH1AGA	[HINO Profia]	2017~2019	83
2KG-FN1AGA		2018~2019	5
2PG-FN1AJA		2017~2019	9
2PG-FQ1AJG		2017~2019	63
2PG-FR1AGA		2017~2019	74
2DG-FR1AJA		2017~2019	55
2PG-FR1AJG			
2PG-FS1AGA		2017~2019	2,862
2PG-FS1AJA		2017~2019	304
2KG-FS1EGA		2017~2019	763
2DG-FS1EJA		2017~2019	190
2KG-FS1EJA			
2PG-FW1AHG		2018~2018	6
2PG-FW1AJG		2018~2018	2
			TOTAL