

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2933	DATE	October 3, 2019
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	The battery-positive cable links the battery with the power distribution box which supplies electric power to the vehicle. Due to inappropriate metal coating material and configuration of the connector of the battery-positive cable, corrosion may occur by vehicle vibration and contact resistance may increase. This results in insufficient electric power supply from the power distribution box to the vehicle electrical components. In worst case, engine may stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADC-3N1M	D3 Biturbo	2009-2010	38
	D3 Biturbo Coupe	2009-2010	11
ADC-3N1A	D3 Biturbo	2009-2010	37
	D3 Biturbo Touring	2009-2010	20
ABA-3K2H	B3 Biturbo Toruing 4WD	2009-2010	4
ABA-3K30	B3S Biturbo Toruing 4WD	2010	4
		TOTAL	114