

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2938	DATE	October 15 th , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In the inline 4-cylinder engine of the subject vehicle, due to insufficient press-in force for the bushes of the counterbalance shaft bearing, there is a possibility that the bush could become loose by engine heat and vibration. If this were to occur, the abnormal noise will occur and the engine will be damaged.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-5F20	BMW 320i	2018 - 2019	35
	BMW 330i	2018 - 2019	10
ABA-JR20	BMW 530i	2018	2
ABA-JT20	BMW 530i Touring	2018 - 2019	4
ABA-JX20S	BMW 630i Gran Turismo	2018	1
3BA-HF20	BMW Z4 sDrive 20i	2018 - 2019	4
		TOTAL	56