

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4575	DATE	Oct.17, 2019
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to insufficient durability evaluation of brake fluid pressure for the brake hose, certain vehicles are equipped with hose fitting caulking area with an insufficient sealing. As the result, the brake fluid may squeeze its way between the hose's inner and outer layer, causing brake hose to bulge.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GK6	「IMPREZA」	2016 ~ 2018	3,432
DBA-GK7		2016 ~ 2018	5,947
DBA-GT6		2016 ~ 2018	10,843
DBA-GT7	「IMPREZA」 「XV」	2016 ~ 2018	38,642
		TOTAL	58,864