

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

<b>CAMPAIGN No.</b>	<b>4581</b>	<b>DATE</b>	<b>October 17, 2019</b>
<b>MANUFACTURER</b>	<b>SUZUKI MOTOR CORPORATION</b>		
<b>DESCRIPTION OF DEFECT</b>	<p>Due to improper inner structure of the fuel injector, the discharge quantity of fuel from the fuel injection system increases while using.</p> <p>If fuel quantity is increased, CO content in the exhaust gas rise up and it may infringe Japanese emission standard.</p>		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLE</b>
<b>2BL-CP52A</b>	<b>SKYWAVE</b>	<b>2017-2018</b>	<b>206</b>
		<b>TOTAL</b>	<b>206</b>