

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

|                       |  |      |                 |
|-----------------------|--|------|-----------------|
| CAMPAIGN No.          | 4582   | DATE | October 17,2019 |
| MANUFACTURER          | MITSUBISHI MOTORS CORPORATION  |      |                 |
| DESCRIPTION OF DEFECT | An incorrect number that is different from the Regulation-approved one was imprinted on the lenses of some side turn lamps due to an improper control of the molding die of the lens. As a result, some side turn lamps may not conform to“Safety Regulations for Road Vehicles”, Article 41 (Direction Indicator Lamp). |      |                 |

| TYPE     | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|-----------------|---------------------|-------------------|
| ZAA-HD4W | 「i-MiEV」        | 2019                | 18                |
|          |                 | TOTAL               | 18                |

The parts for which the vehicle can not be identified because it was shipped as service parts

| Part Name           | Part No. | Delivery Period of the part | Quantity |
|---------------------|----------|-----------------------------|----------|
| SIDE TURN LAMP ASSY | MR522027 | 2019                        | 15       |