

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4586	DATE	18 October 2019
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>The road roller has the following issues. The fuel tank of the road roller has been installed without a breather due to improper cap selection. For this reason, fuel cannot be supplied to the engine and the engine rpm becomes unstable. In the worst case, the engine stop and suddenly brake during running.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	「ZC35C-5」	2019	1
—	「ZC50C-5」	2019	1
—	「HW41VWH-6」	2019	1
		TOTAL	3