

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4587	DATE	October 29, 2019
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>Since the shape of the hydrostatic transmission hose of the agricultural tractor is inappropriate, the hose may come into contact with the frame, and the hose may be worn due to running vibration. Therefore, if the use is continued as it is, the hose is damaged and the hydraulic oil leaks, and in the worst case, there is a possibility that the vehicle cannot run.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
—	「YT5113C」	2015~2017	242	
—	「YT5113AC」	2017~2019	68	
	「TA-C1130」	2018~2019	10	
	「GCR1130」	2019	6	
		TOTAL	326	