

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai-2943	Date	October 29, 2019
Manufacturer	Jaguar Cars Limited (Japanese Importer: Jaguar Land Rover Japan Limited)		
Description of defect	A concern has been identified on certain 2020 Model Year Range Rover Evoque vehicles where the fuse in the Engine Junction Box for the front or rear windshield washer system may fail should the system be operated in freezing or blocked conditions. An interpretation from Society of Automotive Engineers (SAE) J942 and other similar standards makes clear the requirement for washers to operate following a frozen state operation.		

Type	Commercial name	Model year recalled	Number of vehicles
3DA-LZ2NA	Range Rover Evoque	2020	148
5BA-LZ2XA	Range Rover Evoque	2020	190
7BA-LZ2XAP	Range Rover Evoque	2020	92
Unknown	Range Rover Evoque	2020	1
Total			431