

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4595	DATE	October 31, 2019
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the certain passenger airbag inflator, some propellants in inflator may deteriorate due to the prolonged exposure to temperature cycling under humid condition. Therefore, during the airbag deployment, the container of inflator may be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GG3P	Mazda 「ATENZA」	2005-2007	1,351
DBA-GG3S		2005-2007	2,856
DBA-GY3W CBA-GY3W		2005-2007	2,927
DBA-GGEP		2005-2007	1,191
DBA-GGES		2005-2007	561
DBA-GYEW		2005-2007	778
		TOTAL	9,664